

More safety for stable walkways, washdown and key areas

Rubber in stable walkways and in washdown areas? What at first seems like a luxury should actually be standard in a horse stable. Concrete floors and horseshoes are not a good combination when the risk of injury for animals and humans should be as low as possible.



Where can slipping hazards occur?

Slipping hazards can occur, for example, when turning into the loosebox – here the horse usually has to make a **tight turn**. Horses often do not stand completely still when being hosed down in the washdown area or at the vet's and farrier's. Concrete or cobblestones do **not** offer **sufficient sure-footedness** for the four-legged friends. Especially with rather restless young animals, this often **increases their nervousness**.

More comfort, less noise

The BELMONDO® Walkpro provides more safety in stable walkways, washdown and key areas. It offers optimized wet slip resistance in an attractive and **easy to care mosaic design**. Also pleasant: the loud **clatter of hooves** in the stable **is reduced** significantly. The 16 mm thick mat with interlocking joints is suitable for higher loads due to its top layer and is suitable for vehicle traffic. The exact puzzle ensures easy installation of the square metre mats.

Experiences with BELMONDO® Walkpro in Schwaiganger, DE

"We've noticed that our horses – especially the younger animals – feel quite secure on BELMONDO® mats. The horses are much calmer now at the washdown area than when they stood on concrete. Even tight turns don't make them nervous anymore."

Ludwig Rummelsberger, Main and State Stud Farm Schwaiganger

